

Title:	RN DS-K1T501SF/500S v1.1.0 101819NA	Version:	v1.1.0	Date:	101819
Product:	DS-K1T501SF/500S	Build:	20190718	Page:	1 of 5
Action Required:	None, Information Only				

■ General Information

Firmware for the following products have been updated to add new features:

Device Model	Firmware Versions and Builds
DS-KH8301-WT	v1.5.0_181031
DS-KH8300-T	v1.5.0_181031
HikConnect	v3.9.1

NOTE: To complete the upgrade, manually restore default settings after new firmware installation.

■ v1.1.0_20190718 (Current Version)

• New Features

- Private SIP is the default protocol, but Standard SIP is also supported. The two protocols can be switched in the SDK Demo.
- The logic design that calls iVMS-4200 with a long press has been deleted. Until now, if K1T501 was added to the Hik-Connect app, indoor station, and iVMS-4200, pressing the call button would call all of the latter products at the same time.
- When indoor stations connect to door stations, there is now an 'Enable' icon that triggers two-way audio between the two products (this feature is only supported in private SIP mode, and not in standard SIP mode). Also, this feature is only available for first generation indoor stations.

• Bug Fixes

- When an unauthorized card was swiped at a door station, the indoor station would be called automatically.
- When the K1T501 device was registered as a sub door station and the indoor station was selected in the live view interface, the sub door station would not be displayed.

■ v1.1.0_20180801 (Previous Version)

• New Features

- The indoor station can unlock the door in card reader mode.
- The indoor station v1.5.0 build has been integrated.

Title:	RN DS-K1T501SF/500S v1.1.0 101819NA	Version:	v1.1.0	Date:	101819
Product:	DS-K1T501SF/500S	Build:	20190718	Page:	2 of 5
Action Required:	None, Information Only				

■ v1.1.0_20180801 (Previous Version)

• Bug Fixes

- When a device connected to the Hik-Connect app and the unlock icon was clicked, the user would be prompted to change their unlock password.

■ v1.1.0_20180629 (Previous Version)

• New Features

- DHCP function is supported.
- When the indoor station is added to Hik-Connect and a button on the K1T500/K1T501SF is pressed, the indoor station and Hik-Connect ring at the same time.
- Hik-Connect is supported directly.
- DST settings are applied by default in North America.

• Bug Fixes

- The WPA2 Wi-Fi bug has been fixed.

■ v1.1.0_20171121 (Previous Version)

• New Features

- NVR connection, and the recording of motion detection or scheduled video is supported.
- Alarm message and recorded videos can be uploaded to the NVR.
- Alarm message types can be distinguished from one another.

■ Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance and will take effect automatically after upgrading from previous versions. This document was created to inform you about the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Title:	RN DS-K1T501SF/500S v1.1.0 101819NA	Version:	v1.1.0	Date:	101819
Product:	DS-K1T501SF/500S	Build:	20190718	Page:	3 of 5
Action Required:	None, Information Only				

■ NOTES

- Hikvision has all rights to alter, modify, and/or cancel this notice.
- Hikvision doesn't provide any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.