

<b>Title:</b>	RN Value Express ERI-Q10x-Px 4 MP NVRs	<b>Version:</b>	v3.4.96	<b>Date:</b>	031419
<b>Product:</b>	ERI-Q10x-Px NVRs	<b>Build:</b>	190225	<b>Page:</b>	1 of 1
<b>Action Required:</b>	None, Information Only				

### ■ General Information

Affected Products	
Value Express 4 MP NVR	ERI-Q104-P4 ERI-Q108-P8

### ■ Fixed Issue

An artifact line appeared on the display when the NVR was connected to a non-Value Express 4 MP IPC.

### ■ Notes

- Hikvision has all rights to alter, modify, and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.