

Title:	RN NVR v4.1.63 013119NA	Version:	v4.1.63	Build:	181106
Product:	I Series Super NVRs	Date:	013119	Page:	1 of 1
Action Required:	None, Information Only				

Network Video Recorder v4.1.63, Build 181106 (External)

Firmware Basic Information	Firmware Version:	V4.1.63
	SDK Version:	V5.3.6.41
	Play Library (PlayCtrl.dll)	7.3.3.67
	Web Component:	V4.0.11build181227
	iVMS-4200:	V2.6.11.7 build20181227
	OpenSDK Version:	V1.5.55 build 180925

■ Related Products List

I Series NVR	DS-96064NI-I16 DS-96128NI-I24/H DS-96256NI-I24/H
--------------	--

■ Reason for Upgrade

Optimize product performance.

■ Fixed Issues

- NVR failure when NVR with multiple (more than one) HDD is added to Hik-Central
- NVR stops recording if time synchronization (NTP, Hik-Central, etc.) occurs within a minute after DST time shift
- Large database causes search and file read/write failure

■ Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance and will take effect automatically after upgrading from previous versions.

For questions or concerns, please contact our local technical support team.

NOTE:

Hikvision has all rights to alter, modify, and cancel this notice.

Hikvision does not give any guarantee for old model stock.

Hikvision is not liable for any typing or printing errors.

For special model change details, please contact our local technical support team.